REPORT DOCUMENTATION PAGE				Form Approved			
				OMB No. 0704-0188			
maintaining the data including suggestion Dayis Highway, Sui	needed, and completing is for reducing this burder to 1204. Arlington, VA	and reviewing this collect to Department of Defent 22202-4302. Respondents	tion of information. Send comm use, Washington Headquarters So s should be aware that notwithst	ents regarding this burde ervices, Directorate for I anding any other provisi	ewing instructions, searching existing data sources, gathering and en estimate or any other aspect of this collection of information, information Operations and Reports (0704-0188), 1215 Jefferson on of law, no person shall be subject to any penalty for failing to IRN YOUR FORM TO THE ABOVE ADDRESS.		
1. REPORT D		2. REPORT T		3. DATES COV			
		Viewgraphs					
4. TITLE AND	4. TITLE AND SUBTITLE			5a. CONTRACT NUMBER			
Paduaina NVC	Daducing NVC Deleted Special Disorientation Michans			5b. GRANT NUMBER			
Reducing NVG-Related Spatial Disorientation Mishaps				5c. PROGRAM ELEMENT NUMBER			
6. AUTHOR(S)				5d. PROJECT NUMBER			
Joseph Antonio				5e. TASK NUMBER			
				5f. WORK UNIT NUMBER			
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)			D ADDRESS(ES)	8. PERFORMING ORGANIZATION REPORT NUMBER			
22347 Cedar P	fare Center Aircraf oint Road, Unit #6 , Maryland 20670-						
			(S) AND	10. SPONSOR/MONITOR'S ACRONYM(S)			
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10,20,00,000,000,000			
ADDRESS(ES)				11 GRONGOD A COMETOR IS REPORT MILL (DER (S)			
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)			
12. DISTRIBU	TION/AVAILABI	ITY STATEMEN	T				
Approved for public release; distribution is unlimited.							
	ENTARY NOTES						
20,000							
14. ABSTRAC	T	1.144.0730					
11.712011010	•						
15. SUBJECT TERMS							
16. SECURITY	CLASSIFICATIO	N OF:	17. LIMITATION	18. NUMBER	19a. NAME OF RESPONSIBLE PERSON		
			OF ABSTRACT	OF PAGES	Joseph Antonio		
a. REPORT	b. ABSTRACT	c. THIS PAGE			19b. TELEPHONE NUMBER (include area		
					code)		
Unclassified	Unclassified	Unclassified	SAR	5	(301) 342-9283		

Standard Form 298 (Rev. 8-98) Prescribed by ANSI Std. Z39-18



## Recent Trends in Spatial Disorientation Research

November 15 - 17, 2000 San Antonio, Texas

#### Reducing NVG-Related Spatial Disorientation <u>Mishaps</u>

Joseph C. Antonio, MD Crew Systems Department Naval Air Warfare Center – Aircraft Division Patuxent River, Maryland

### Introduction

#### • Purpose

 Provide recipe for success in helping decrease NVG-related CFIT mishaps

#### • Disclaimer

 Opinions are those of the briefer and do not represent official Navy position

# Making Rabbit Stew

What is the first thing to do when making rabbit stew?

Making Rabbit Stew	
Muning Rubbit Stew	
Find and catch the rabbit.	
<b></b>	
	•
	,
	1 .
Reducing NVG-Related CFIT	
Mishaps	
Transition po	
What is the first thing to do when attempting to	·
reduce the occurrence of NVG-related CFIT	
mishaps?	
	1
Padusing NVC Polated CEIT	
Reducing NVG-Related CFIT	
Mishaps	
Find the primary cause and provide solutions.	
2 promise promise provide a series provide provi	

# Primary Cause

- Factors leading to NVG-related CFIT mishaps
  - Task saturation
  - Breakdown of crew coordination
  - Fatigue
  - Poor judgment
  - Complacency
  - Overconfidence
- What is culminating event?
  - Breakdown in instrument crosscheck

### **Potential Solutions**

- · Assumption is made that breakdown in instrument crosscheck is the primary cause for **NVG-related CFIT mishaps**
- · Discussion about solutions divided into three topics
  - Design efforts

  - TrainingOperational tools
- · May require new thinking in order to provide help before the mishap
  - Another way of saying that some of the recommendations may be controversial

## Design Efforts 1

- · Software changes and upgrades (requires early prioritization)
  - Cursor control
  - Decision making algorithms
- · Commonality in crewstation design within platform types
  - Habit pattern same for each aircraft
- · Layout of instrument panel
  - Keep same for left and right seats
  - Group primary flight instruments to allow for quick scan
- · HMD design considerations
  - Poor requirements may lead to added workload
     Keep it simple


# Design Efforts 2

- **NVIS** interior lighting
  - Good lighting design more critical when using NVGs
     Instruments scanned quickly
     Habit pattern established with previous lighting
  - Primary flight instrument readability more important than compatibility with NVGs
- · NVIS exterior lighting

  - Can help with sorting
     Improved section/division integrity
- Improved NVG performance and FOV

  - Fusion with other sensors
  - Improved low light capability

### Training

- Introduce NVGs and scan requirements during all phases of flight training (e.g., primary, basic, etc.)

  Easier to establish a pattern than to change one

  Determine how "normal" instrument scan differs from scan when using NVGs and train to those differences
- Begin NVG flight training during low illumination

   Creates the right impression upfront
- Add SD-inducing profiles to simulator training
  - Re-create events leading to previous mishaps
- Integrate with regular simulator training sorties
- Insure ground, simulation, and flight training correlate to reinforce instrument crosscheck
  - Training for each typically created in a box. Need to insure they interact effectively.

### **Operational Tools**

- · Realistic guidance for low illumination
  - Current value of .0022 lux is not accurate for current NVG technology
- Should be based on data agreed to by all parties
- Improved tools for preflight planning

  - Risk management
     Current and accurate light level planning calendars
- Track experience via event-based data and use a matrix tied to critical experience criteria
- NVG flight time is not an accurate indicator of experience
- Insure distribution of NVGs is based on mission requirements
  - Aircrew flying missions requiring enhanced detail (e.g., low illumination masking, low altitude over low contrast terrain, etc.) should have the NVG with the best performance


# Summary

NVGs have been in use for a number of years but there are still lessons to be learned. There is no need to wait for the next mishap to take action. Being proactive may result in saved lives and will help win the war of attrition. This may require a new way of looking at the way business is being conducted.

 ***************************************			
			•.